Click here to return to main document and Bookmarks

ATTACHMENT A

Identification of Photographs
November 3, 1992 Site Visit - Western Sand & Gravel

Photograph No.	Description
1	Site From South Gate
2	Example of Posted Signs - West Side
3	Pooled Water - Central Drainage Swale - North Leg
4	Example of Sparse Vegetation with Moss - Top of Cap
5	Example of Slight Depressions - Top of Cap
6	Small Animal Hole with Animal Signs (Corn Kernels)
7	Animal Burrow - North Side Inside Fence
8	Animal Burrow - North Side Inside Fence
9	Example of Hole Under Fence - North Side with Animal Trail
10	Northwest Drainage Structure Inside Fence
11	Northeast Drainage Structure Outside Fence
12	Northwest Drainage Structure Outside Fence
13	View of Southwest Side of Site Outside Fence
14	View of Erosion Gully Near Southwest Drainage Structure Outside Fence
15	Well C4D as Found
16	Well C North Side of Site Outside Fence
17	Well C4B
18	Well E - West Side of Site Outside Fence
19	Well C2D
20	Well C2S
21	Wells - C5 Group
22	Wells - North Side of Site
23	Drums Found Within Fence - North Side (Labelled Non-Hazardous)
24	Stressed Vegetation East Side of Cap Within Fence

1

2

3

4

5

6

7

8

9

10

Click here to view photos 13 - 24