Weekly Progress Summary

Delmont, PA

Photos

Text

Carbondale, Illinois

SES Job No.

E-717

© Copyright 2006, Sevenson Environmental Services, Inc.
All rights reserved

Distribution:

Mike Slenska
Mark Gravelding
Mason Wheeler
Les Halliday
Ben Huggins
Carolyn Bury

Weekly Project Summary No.

66

Work Performed Dates:

July 31 - August 6, 2006

Photo 1

PLACING CA-6 STONE OVER THE NEW EAST-WEST CULVERT ALONG THE ENTRANCE ROAD

Photo 2

EXCAVATING FOR THE 2 - 6 INCH DRAIN PIPES

Photo 3

DISASSEMBLY OF MOD-U-TANK

Photo 4

LOADING OUT CUT UP PIECES OF MOD-U-TANK LINER

Photo 5

PLACING AND FLATTENING OUT CUT UP PIECES OF MOD-U-TANK LINER ON TOP OF THE CAMU

Photo 6

LABORERS STACKING MOD-U-TANK HARDWARE ONTO PALLETS FOR DEMOB

Text

General Comments:

THIS WEEKS SUMMARY OF WORK ACTIVITIES INCLUDE:

FORMER PROCESS AREA SURFACE COVER

* **COMPLETED INSTALLATION OF NEW EAST-WEST CULVERT IN LOW AREA ALONG NORTH EDGE OF FORMER PROCESS AREA SURFACE COVER**

MOD-U-TANK

* **CONTINUING DISASSEMBLY OF MOD-U-TANK**
* **CONTINUING STABILIZATION OF FREE LIQUIDS AND TANK LINER AND PLACING ON CAMU**

MISCELLANEOUS

* **CONTINUING TO EXAMINE AND MAINTAIN EROSION AND SEDIMENTATION CONTROLS**
* **CONTINUING TO DO DAILY WORK SITE AIR MONITORING TO INSURE NO ACTION LEVELS ARE EXCEEDED**