ATTACHMENT 4
RADIO MATERIALS CORPORATION
FOUNTAIN WARREN COUNTY HEALTH DEPARTMENT INSPECTION PHOTOS – AUGUST 21, 2015

Photo 1	9:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 1.	

Photo 2	9:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 1.	

Photo 3	9:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 1.	

Photo 4	10:03 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 1.	

Photo 5	10:05 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Between Buildings 1 and 2.	

Photo 6	10:05 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 7	10:06 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 8	10:07 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 9	10:08 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 10	10:08 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 11	10:10 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 12	10:10 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 13	10:10 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 14	10:10 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 15	10:10 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 16	10:11 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 17	10:12 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 18	10:12 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 19	10:12 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 20	10:12 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 21	10:13 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	



Photo 22	10:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	



Photo 23	10:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	



Photo 24	10:15 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	

Photo 25	10:15 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2. Chemical storage.	



Photo 26	10:18 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	

Photo 27	10:19 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	

Photo 28	10:19 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	

Photo 29	10:19 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	



Photo 30	10:20 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	



Photo 31	10:21 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	



Photo 32	10:22 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	

Photo 33	10:22 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	

Photo 34	10:24 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	



Photo 35	10:25 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	



Photo 36	10:25 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	



Photo 37	10:26 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	

Photo 38	10:26 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 3.	

Photo 39	10:27 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Between Buildings 2 and 3.	

Photo 40	10:27 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 41	10:28 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 42	10:28 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 43	10:31 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 44	10:32 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 45	10:33 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 46	10:33 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 47	10:34 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 48	10:34 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 49	10:34 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 50	10:34 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 51	10:35 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 52	10:35 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 53	10:35 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 54	10:35 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 55	10:35 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 56	10:36 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 57	10:36 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 58	10:37 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 59	10:37 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 60	10:37 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 61	10:37 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 62	10:38 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	



Photo 63	10:39 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 64	10:39 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 65	10:39 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 66	10:39 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 67	10:39 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4.	

Photo 68	10:42 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	

Photo 69	10:42 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	



Photo 70	10:43 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	

Photo 71	10:43 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	

Photo 72	10:44 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	

Photo 73	10:45 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	

Photo 74	10:47 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	



Photo 75	10:48 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 4B.	

Photo 76	10:48 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Outside Quality Control Room.	

Photo 77	10:48 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Outside Quality Control Room.	

Photo 78	10:49 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Outside Quality Control Room.	

Photo 79	10:49 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Outside Quality Control Room.	

Photo 80	10:48 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Outside Quality Control Room.	

Photo 81	10:50 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Quality Control Room.	



Photo 82	10:50 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Quality Control Room.	



Photo 83	10:50 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Quality Control Room.	



Photo 84	10:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Quality Control Room.	



Photo 85	10:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Quality Control Room.	

Photo 86	10:57 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Quality Control Room.	

Photo 87	10:58 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	

Photo 88	10:58 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 2.	



Photo 89	11:05 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 90	11:05 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 91	11:05 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 92	11:06 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 93	11:06 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 94	11:06 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 95	11:07 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 96	11:08 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 97	11:08 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 98	11:09 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 99	11:13 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana

Photo 100	11:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 101	11:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 102	11:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 103	11:14 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 104	11:15 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 105	11:19 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 106	11:20 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 107	11:21 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 108	11:21 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 109	11:22 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 110	11:22 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 111	11:25 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 112	11:25 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	

Photo 113	11:33 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 5.	



Photo 114	11:51 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 115	11:51 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 116	11:51 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 117	11:51 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 118	11:52 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 119	11:52 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 120	11:52 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 121	11:52 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 122	11:52 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 123	11:53 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 124	11:53 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 125	11:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	



Photo 126	11:54 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 127	11:55 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 128	11:55 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 129	11:56 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 130	11:56 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 131	11:56 am EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Building 8.	

Photo 132	12:00 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	

Photo 133	12:00 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	

Photo 134	12:01 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	

Photo 135	12:01 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	

Photo 136	12:02 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	

Photo 137	12:02 pm EDT August 21, 2015 Radio Materials Corporation, Attica, Indiana
Recovery system outside Buildings 6-7.	