

**Pump Station Inspection Summary
Guam Waterworks Authority**

Pump Station Name	Wastewater District	WWTP Name	Date Inspected	No. of Pumps	No. of Operational Pumps	Stand-by Generator Status	Alarms/ Telemetry Status	NEIC Photo Reference
Fujita	Northern	Northern District	4/27/12	4	4	On-site, maintained by USSI	Full telemetry	40 - 46
Route 16 (Liguan Terrace)	Northern	Northern District	4/27/12	4	2	On-site, maintained by USSI	None	47 - 50
Double Trouble	Northern	Northern District	4/27/12	2	2	On-site, maintained by GPA	None	51 - 54
PGD	Northern	Northern District	4/27/12	2	2	On-site, maintained by GWA	None	55 - 57
Hafa Adai	Northern	Northern District	4/27/12	2	2	On-site, maintained by GWA	None	58 - 60
Santa Ana	Northern	Northern District	4/27/12	2	2	Out of service for 2 years	None	61 - 63
Harmon	Northern	Hagatna	5/1/12	2	2	On-site, maintained by USSI	None	124 - 127
Southern Link	Northern	Northern District	5/1/12	4	4	On-site, maintained by USSI	Full telemetry	128 - 134
New Chaot (with Old Chaot, out of service)	Central	Hagatna	4/30/12	3	3	On-site, maintained by USSI	High wet well level sensors trigger cell phone call	72 - 83
Dairy Road	Central	Hagatna	4/30/12	2	2	On-site, maintained by contractor	None	84 - 90

**Pump Station Inspection Summary
Guam Waterworks Authority**

Pump Station Name	Wastewater District	WWTP Name	Date Inspected	No. of Pumps	No. of Operational Pumps	Stand-by Generator Status	Alarms/Telemetry Status	NEIC Photo Reference
Mangilao	Central	Hagatna	4/30/12	2	2	On-site, maintained by GPA	None	91 - 96
Namo	Central	Hagatna	5/1/12	2 ejectors	1 ejector	None	None	101 - 105
Casimero	Central	Hagatna	5/1/12	2	2	None	None	106 - 108
Mongmong	Central	Hagatna	5/1/12	2	2	On-site, maintained by contractor	None	109 - 111
Agana Main	Central	Hagatna	5/1/12	4	3	On-site, maintained by contractor	None	112 - 116
Mamajanao	Central	Hagatna	5/1/12	3	2	On-site, maintained by Morrico	None	117 - 123
Chaligan	Southern	Agat	4/25/12	2	2	On-site, maintained by GWA	Full telemetry	1 - 3
Ga'an	Southern	Agat	4/25/12	3	3	On-site, maintained by USSI	Full telemetry	6 - 8
Umatac-Merizo PS 12	Southern	Umatac-Merizo	4/25/12	2	2	On-site, maintained by GPA	None	12 - 15
Umatac-Merizo PS 14	Southern	Umatac-Merizo	4/25/12	2	2	On-site, maintained by GPA	None	16 - 18
Umatac-Merizo PS 17	Southern	Umatac-Merizo	4/25/12	2	2	On-site, maintained by GPA	None	19 - 20
Umatac-Merizo PS 18	Southern	Umatac-Merizo	4/25/12	2	2	On-site, maintained by GPA	None	21 - 23

Pump Station Inspection Summary
Guam Waterworks Authority

Pump Station Name	Wastewater District	WWTP Name	Date Inspected	No. of Pumps	No. of Operational Pumps	Stand-by Generator Status	Alarms/ Telemetry Status	NEIC Photo Reference
Umatac-Merizo PS 13	Southern	Umatac-Merizo	4/26/12	2	2	On-site, maintained by GPA	None	24 - 25
Umatac-Merizo PS 20	Southern	Umatac-Merizo	4/26/12	2	1	On-site, maintained by GPA	None	29 - 30
Umatac-Merizo PS 19	Southern	Umatac-Merizo	4/26/12	2	2	On-site, maintained by GPA	Full telemetry	31 - 33
Inarajan Lift	Southern	Inarajan	4/26/12	2	2	On-site, maintained by Morrico	None	34 - 36
Inarajan Main	Southern	Inarajan	4/26/12	2	1	On-site, maintained by Morrico	None	37 - 39
Talofofu	Southern	Baza Gardens	5/3/12	2	1	On-site, maintained by USSI	None	142 - 147